Cotswold District Council

Updating and Screening Assessment



In fulfillment of Part IV of the Environment Act, 1995 - Local Air Quality Management

July 2009

Contact Details

Local Authority Officer	Hilary Beach

Department	Environmental Services			
Address	Trinity Road,			
	Cirencester,			
	Gloucestershire,			
	GL7 1PX			
Telephone	01285 623000			
e-mail	hilary.beach@cotswold.gov.uk			

Report Reference	Updating and Screening Assessment, 2009
Date	July 2009

i

Executive Summary

This Updating and Screening report for 2009 is the next round of reporting on air quality required of local authorities. It considers new Technical Guidance (LAQM.TG(09)) issued by Defra and the Devolved Administrations. This guidance was produced using experience and knowledge gained from previous reporting rounds.

Cotswold District Council has continued to maintain 20 diffusion tube monitoring sites for nitrogen dioxide across the district. The sites are representative of relevant exposure and relate to emissions from traffic, with the exception of one background site which is maintained in a rural location. Diffusion tube monitoring for benzene had been carried out over a number of years, no issues were identified at any locations and with consistently low results this monitoring has now ceased.

Following the assessment of 2005 monitoring, further work was undertaken to confirm the need to declare an Air Quality Management Area (AQMA) and identify the spatial extent of the area. For this, automatic monitoring was undertaken during 2007. In April 2008 Cotswold District Council declared an AQMA at the busy junction on the A417 trunk road. This was for nitrogen dioxide from road vehicle emissions and there are residential properties in the area. A new site for automatic monitoring was established within the AQMA this will be reported on later in 2009 in a Further Assessment Report and the Council is currently working on an Air Quality Action Plan for this AQMA.

The conclusion from this round of screening assessment is that Cotswold District Council will need to proceed to a Detailed Assessment for Thames Street, Lechlade as the diffusion results indicate an exceedance of the nitrogen dioxide annual mean air quality objective.

No other areas have been identified for Detailed Assessment. The Council will submit a Progress Report and Detailed Assessment in 2010.

Table of Contents

Cor	ntact	Details	i
Exe	cutiv	e Summary	ii
Tab	le of	Contents	iii
List	of Ta	ables	v
List	of Fi	gures	vi
1		oduction	1
-	1.1	Description of Local Authority Area	1
	1.2	Purpose of Report	1
	1.3	Air Quality Objectives	2
	1.4	Summary of Previous Review and Assessments	4
2	Nev	Monitoring Data	6
	2.1	Summary of Monitoring Undertaken	6
	2.2	Comparison of Monitoring Results with AQ Objectives	8
3	Roa	d Traffic Sources	11
	3.1	Narrow Congested Streets with Residential Properties Close to the Kerb	11
	3.2	Busy Streets Where People May Spend 1-hour or More Close to Traffic	11
	3.3	Roads with a High Flow of Buses and/or HGVs.	12
	3.4	Junctions	12
	3.5	New Roads Constructed or Proposed Since the Last Round of Review and Ass	sessment
		12	
	3.6	Roads with Significantly Changed Traffic Flows	12
	3.7	Bus and Coach Stations	12
4	Oth	er Transport Sources	13
	4.1	Airport	13
	4.2	Railways (Diesel and Steam Trains)	13
	4.3	Ports (Shipping)	13
5	Indu	ustrial Sources	14
	5.1	Industrial Installations	14
	5.2	Major Fuel (Petrol) Storage Depots	14
	5.3	Petrol Stations	14
	5.4	Poultry Farms	15
6	Con	nmercial and Domestic Sources	16
	6.1	Biomass Combustion - Individual Installations	16
	6.2	Domestic Solid-Fuel Burning	16
7	Fug	itive or Uncontrolled Sources	18
8	Con	clusions and Proposed Actions	19

11	App	pendix C - Maps of monitoring locations	25
10	App	pendix B: List of Registered Processes	22
	9.3	QA/QC of diffusion tube monitoring	20
	9.2	QA/QC of automatic monitoring	20
	9.1	Diffusion Tube Bias Adjustment Factors	20
9	App	pendix A: QA:QC Data	20
	8.3	Proposed Actions	19
	8.2	Conclusions from Assessment of Sources	19
	8.1	Conclusions from New Monitoring Data	19

List of Tables

Table 1: Air Quality Objectives included in Regulations for the purpose of Local Air Quality	
Management in England.	3
Table 2: Summary of the Round 3 of Review and Assessment	4
Table 3: Details of Automatic and Non-Automatic Monitoring Sites	7
Table 4: Results of Automatic Monitoring for Nitrogen Dioxide: Comparison with Annual	
Mean Objective	ć
Table 5: Results of Nitrogen Dioxide Diffusion Tubes	ć
Table 6: Results of Benzene Diffusion Tube	10
Table 7: WASP results for Bristol Scientific Services	21
Table 8: List of LAPPC Permitted Installations on the Public Register	22

List of Figures

Figure 1: Map of the Cotswold area.	2
Figure 2: Birdlip Air Quality Management Area	5
Figure 3: Cotswold monitoring sites	25
Figure 4: Todenham Road monitoring site	26
Figure 5: Birdlip monitoring sites	27
Figure 6: Bourton-on-the-Water monitoring site	28
Figure 7: Cirencester monitoring sites	29
Figure 8: Fairford monitoring sites	30
Figure 9: Lechlade monitoring site	31
Figure 10: Moreton-in-Marsh monitoring site	32
Figure 11: Stow Lodge monitoring site	33
Figure 12: Stow-in-the-Wold monitoring site	34
Figure 13: Tetbury monitoring site	35

1 Introduction

1.1 Description of Local Authority Area

Cotswold District Council is predominantly a rural area, geographically the largest of the Gloucestershire local authorities and crossed by three main traffic routes:

- A419/A417, which is a trunk road crossing from northwest to southeast;
- A429 southwest to northeast; and
- A40 which crosses the district west to east.

These roads mainly pass through countryside, bypassing most of the main towns, apart from the A429 that passes through the outskirts of Stow-on-the-Wold and Moreton-in-Marsh (Figure 1). Large portions of the District are classified as an area of outstanding natural beauty.

There are no industrial areas within the district or close by that make a significant impact on air quality. The industries within the district that emit any of the prescribed pollutants are not located close to relevant public exposure. The scale on which they operate does not produce emissions that contribute significantly to the air quality.

1.2 Purpose of Report

This report fulfils the requirements of the Local Air Quality Management process as set out in Part IV of the Environment Act (1995), the Air Quality Strategy for England, Scotland, Wales and Northern Ireland 2007 and the relevant Policy and Technical Guidance documents. The LAQM process places an obligation on all local authorities to regularly review and assess air quality in their areas, and to determine whether or not the air quality objectives are likely to be achieved. Where exceedences are considered likely, the local authority must then declare an Air Quality Management Area (AQMA) and prepare an Air Quality Action Plan (AQAP) setting out the measures it intends to put in place in pursuit of the objectives.




Figure 1: Map of the Cotswold area.

1.3 Air Quality Objectives

The air quality objectives applicable to LAQM in England are set out in the Air Quality (England) Regulations 2000 (SI 928), The Air Quality (England) (Amendment) Regulations 2002 (SI 3043), and are shown in Table 1. This table shows the objectives in units of microgrammes per cubic metre $\mu g/m^3$ (milligrammes per cubic metre, mg/m^3 for carbon monoxide) with the number of exceedences in each year that are permitted (where applicable).

Table 1: Air Quality Objectives included in Regulations for the purpose of Local Air Quality Management in England.

Pollutant	Air Quality Objective	Date to be	
	Concentration	Measured as	achieved by
Benzene	16.25 <i>μ</i> g/m³	Running annual mean	31.12.2003
	5.00 μ g/m ³	Running annual mean	31.12.2010
1,3-Butadiene	2.25 μg/m ³	Running annual mean	31.12.2003
Carbon Monoxide	10.0 mg/m ³	Running 8-hour mean	31.12.2003
Lead	0.5 <i>μ</i> g/m ³	Annual mean	31.12.2004
	$0.25 \ \mu \text{g/m}^3$	Annual mean	31.12.2008
Nitrogen Dioxide	200 μg/m³ not to be	1-hour mean	31.12.2005
	exceeded more than 18		
	times a year		
	40 μg/m ³	Annual mean	31.12.2005
Particles (PM ₁₀)	50 μ g/m ³ , not to be	24-hour mean	31.12.2004
(gravimetric)	exceeded more than 35		
	times a year		
	40 μg/m ³	Annual mean	31.12.2004
Sulphur Dioxide	350 μ g/m ³ , not to be	1-hour mean	31.12.2004
	exceeded more than 24		
	times a year		
	125 μ g/m ³ , not to be 24-hour mean		31.12.2004
	exceeded more than 3		
	times a year		
	266 μ g/m ³ , not to be	15-minute mean	31.12.2005
	exceeded more than 35		
	times a year		

1.4 Summary of Previous Review and Assessments

Cotswold District Council has submitted Review and Assessment reports to the satisfaction of Defra. Round 1 and Round 2 of Review and Assessment did not identify any air quality issues. The following table summarises the outcome of Round 3 f Review and Assessment.

Table 2: Summary of the Round 3 of Review and Assessment

Report Submitted	Outcome					
Updating and Screening 2006	Diffusion tube monitoring carried out for NO2 and					
	Benzene. No new issues identified. Monitoring continued					
	for NO ₂ at the Air Balloon roundabout junction of the A417					
	at Birdlip in relation to potential exceedance identified.					
Detailed Assessment 2007 for nitrogen	Automatic monitoring undertaken of NO2 and dispersion					
dioxide (NO ₂) at A417 junction	modelling carried out at Birdlip confirmed need to declare					
	AQMA.					
Progress Report 2007	No new issues. Monitoring for NO2 continued with no					
	changes.					
Declaration of Local Air Quality	Exceedance of nitrogen dioxide related to road traffic					
Management Area April 2008	emissions. Long term level from modelling 52.2µg/m ³					
	annual mean this exceeds the Air Quality Objective of					
	40μg/m ³ as annual mean. This is a major trunk route with					
	a high number of HGV's where there are residential					
	properties close by. See Figure 2.					




Figure 2: Birdlip Air Quality Management Area

2 New Monitoring Data

2.1 Summary of Monitoring Undertaken

Within the area where an exceedence of nitrogen dioxide was identified at the Air Balloon junction an automatic chemiluminescence's analyser was operated for seven months. The data from this monitoring confirmed the need to declare an AQMA. Monitoring using diffusion tubes was also used for nitrogen dioxide and benzene. Monitoring at all sites is in relation to emissions from traffic.

2.1.1 Automatic Monitoring Sites

Automatic monitoring for NO₂ was undertaken for seven months April to October 2006 for the Detailed Assessment. The site was maintained AEA Energy and Environment; it was sited at the cottages by the roundabout at the junction of the A419. The conclusions from the monitoring and dispersion modelling indicated that Cotswold District Council should declare an AQMA for this area near Birdlip. In April 2008 an AQMA was declared. (See Figure 2).

For 2009 Cotswold District Council is undertaking six months automatic monitoring within the AQMA at a new site; monitoring commenced in mid January 2009. Co-located diffusion tube monitoring is also being undertaken at this site, the data will be used for a Further Assessment for this AQMA.

2.1.2 Non-Automatic Monitoring

The Council manages 20 diffusion tubes for NO₂ within the district, in 2008 some changes were made to provide co-location monitoring within the AQMA. Tubes are supplied from Bristol Scientific Services; the laboratory prepares the tubes using 50ml of 20% triethanolamine in water. The tube preparation and subsequent analysis follow the procedures in the harmonised "Practical Guidance" document. The results of laboratory precision and WASP scheme are included as an Appendix. The tubes are exposed on a monthly basis. There is no local bias adjustment factor therefore the factor was derived from the National Bias Adjustment Spreadsheet (v05/09). The following bias adjustment factors have been utilised to adjust the data from the diffusion tubes:

- 2006: 0.90 based on 5 studies;
- 2007: 0.77 based on 5 studies; and
- 2008: 0.87 based on 4 studies.

All data has been adjusted where required according to LAQM.TG (09).

Table 3: Details of Automatic and Non-Automatic Monitoring Sites

Site Name	Site Type	OS Grid Reference	Pollutants Monitored	In AQMA? (Y/N)	Relevant Exposure? (Y/N and distance)	Distance to kerb of nearest road (N/A if not applicable)	Worst- case location? (Y/N)
Birdlip Automatic Analyser				1	,		, ,
Birdlip Continuous Analyser (2006)	Roadside	X393446 - Y216182	NO ₂	Υ	Y(1m)	2m	Υ
Birdlip Continuous Analyser (Current)	Roadside	X393459 - Y216124	NO ₂	Υ	Y(<1m)	4m	Υ
Cotswold NO ₂ Diffusion Tube Sites			•	1			
Moreton-in-Marsh - High St CDC office	Roadside	X420495 - Y232490	NO ₂	N	Y (1m)	2m	Υ
Moreton-in-Marsh - High St	Roadside	X420428 - Y232254	NO ₂	N	Y (1m)	2m	N
Stow-in-the Wold - Fosseway Cottage	Kerbside	X419079 - Y226054	NO ₂	N	Y (2m)	1m	Υ
Stow-in-the Wold - A429	Roadside	X419006 - Y225571	NO ₂	N	Υ	8m	Υ
Todenham Road -background site	Rural	X422611 - Y234046	NO ₂	N	N	N/A	N
Bourton-on-the-Water – Landsdown	Kerbside	X416146 - Y220966	NO ₂	N	N	0.5m	Υ
Lechlade - Thames Street	Kerbside	X421378 - Y199501	NO ₂	N	Y (<1m)	<1m	Υ
Fairford – London Rd	Kerbside	X415378 - Y200949	NO ₂	N	Y (1m)	1m	Υ
Fairford - Bridge St	Kerbside	X415167 - Y201004	NO ₂	N	Y(1m)	1m	Υ
Cirencester - Castle Street	Kerbside	X402222 - Y202010	NO ₂	N	Y (<1m)	1m	Υ
Cirencester - London Rd -Waggon/Horses	Kerbside	X402735 - Y201962	NO ₂	N	Y(2m)	1m	Υ
Cirencester- Dollar Street	Roadside	X402159 - Y202290	NO ₂	N	Y(2m)	2m	Υ
Cirencester - Victoria Road	Kerbside	X402779 - Y201667	NO ₂	N	Y(1m)	1m	Υ
Tetbury - Long Street	Kerbside	X389007 - Y193197	NO ₂	N	Y(1m)	1m	Υ
Tetbury – Church St	Kerbside	X389034 - Y193110	NO ₂	N	Y(1m)	1m	Υ
Birdlip x 3 co-located site	Kerbside	X393439 - Y216100	NO ₂	Y	Y(1m)	1m	Υ
Birdlip x 3 co-located site	Kerbside	X393439 - Y216100	NO ₂	Y	Y(1m)	1m	Y
Birdlip x 3 co-located site	Kerbside	X393439 - Y216100	NO ₂	Y	Y(1m)	1m	Y
Birdlip Air Balloon	Kerbside	X393446 - Y216118	NO ₂	Y	Y(1m)	1m	Y
Stow Lodge	Kerbside	X403946 - Y202963	NO ₂	N	Y(5m)	0.5m	Υ

2.2 Comparison of Monitoring Results with Air Quality Objectives

2.2.1 Nitrogen Dioxide

Automatic Monitoring Data

Cotswold District Council undertook automatic monitoring within the AQMA as part of work carried out for the Detailed Assessment for 2007. A chemiluminescence's analyser was used to collect data over 6 months. The results indicated no exceedance of the 1-hour objective through out the 2006 monitoring period. Table 4 illustrates the nitrogen dioxide concentration for this monitoring period. The AQMS monitoring data for 2006 indicated that there was an exceedence of the annual air quality objective for NO₂, however the site was established in June 2006, and there are only 6 months data available. This short term data was annualised to give an annual mean in accordance the then current Technical Guidance (LAQM.TG(03)), resulting in an annual mean NO₂ concentration at the AQMS in 2006 of 52.2µg/m³.

New automatic monitoring began in 2009 within the AQMA this will be reported in the Further Assessment 2009 and Progress Report 2010.

Nitrogen Dioxide Diffusion Tube Monitoring Data

The 2008 bias adjusted nitrogen dioxide concentrations indicate the following sites exceeding of annual mean objective of 40 μ g/m³:

- BIRDLIP: Locations within the Birdlip AQMA show exceedances. (Site 16 Air Balloon 68.9μg/m³). The newer sites at Birdlip are showing that they may have exceedences in future years but these sites only commenced in November 2008 Cotswold will continue monitoring at this location and report data in subsequent Further Assessment and Progress Report 2010.
- LECHLADE: Site 4 Thames Street Lechlade, reports a bias adjusted mean of 43.4 μg/m³ for 2008. Relevant exposure exists at this location. This site was just below the objective in 2007 (39.5μg/m³). Cotswold District Council will be proceeding to a Detailed Assessment for this location in 2010.

Table 4: Results of Automatic Monitoring for Nitrogen Dioxide: Comparison with Annual Mean Objective

Statistic	Period Mean	Estimated	Projected Annual	
	(April 06 –	Annual	Mean	
	October 06)	Mean ^A	2010	
Mean NO ₂	46.0	52.2	45.2	
Maximum 1-hour NO ₂	145	-	-	
99.8 th percentile of hourly means	130	-	-	
Data Capture (%) NO ₂	86%	-	-	

A: (adjusted for short term data capture)

Table 5: Results of Nitrogen Dioxide Diffusion Tubes

Ref	Location	Within	Proportion of	Annual Mean Concs		
		AQMA?	year with valid	(μg/m³) Bias adjusted		adjusted
			data, 2008 (%)	2006	2007	2008
1	Moreton-in-Marsh - High St	N	100	27.2	26.2	30.5
2	Stow-in-the Wold - Fosseway Cottage	N	92	32.6	34.0	36.2
3	Todenham Road (background site)	N	100	12.2	10.8	12.2
-	Bourton-on-the-Water - Landsdown	N	100	14.6	end	-
4	Lechlade - Thames Street	N	92	36.9	39.5	43.4
5	Fairford - London Rd	N	92	32.1	26.0	38.8
6	Fairford - Bridge St	N	100	36.7	32.3	33.1
7	Cirencester - Castle Street	N	100	32.7	29.8	35.2
8	Cirencester -London Rd (Waggon/Horses)	N	100	31.8	31.9	35.2
9	Cirencester- Dollar Street	N	100	24.2	23.2	24.5
10	Cirencester - Victoria Road	N	100	19.2	19.7	22.1
11	Tetbury - Long Street	N	100	29.2	29.8	32.5
12	Tetbury - Church St	N	100	32.5	32.1	37.0
13	Birdlip x 3 co-located site	Y	100	61.2	end	-
14	Birdlip x 3 co-located site	Y	100	63.8	end	-
15	Birdlip x 3 co-located site	Υ	100	56.2	end	-
16	Birdlip -Air Balloon	Υ	100	58.7	54.3	68.1
17	Stow Lodge	N	100	33.9	29.2	34.1
18a	Birdlip - Air Balloon 1	Υ	New site	n/a	n/a	45.9
18b	Birdlip - Air Balloon 2	Y	New site	n/a	n/a	40.4
18c	Birdlip - Air Balloon 3	Y	New site	n/a	n/a	43.2
19a	Birdlip - Air Balloon, beer garden A	Y	New site	n/a	n/a	41.6
19b	Birdlip - Air Balloon, beer garden B	Y	New site	n/a	n/a	30.8
19c	Birdlip - Air Balloon, beer garden C	Υ	New site	n/a	n/a	34.0

2.2.2 PM₁₀

Cotswold District Council has not undertaken any PM₁₀ monitoring since the last round of Updating and Screening Assessments.

2.2.3 Sulphur Dioxide

Cotswold District Council has not undertaken any SO₂ monitoring since the last round of Updating and Screening Assessments.

2.2.4 Benzene

Cotswold District Council has undertaken Benzene monitoring at one site since the last round of Updating and Screening Assessments using a diffusion tube. Concentrations have been consistently low concentration, therefore the monitoring at this site has ceased.

Table 6: Results of Benzene Diffusion Tube

Ref	Location	Within	Annual Mean Concentrations (μg/m³)				
		AQMA?	2006	2007	2008		
3	Todenham Road	N	0.17	0.19	-		

2.2.5 Other pollutants monitored

Cotswold District Council has not undertaken any <u>Carbon Monoxide</u> monitoring since the last round of Updating and Screening Assessments.

Cotswold District Council has not undertaken any <u>Lead</u> monitoring since the last round of Updating and Screening Assessments.

Cotswold District Council has not undertaken any <u>1,3-butadiene</u> monitoring since the last round of Updating and Screening Assessments.

Cotswold District Council has not undertaken any <u>Ozone</u> monitoring since the last round of Updating and Screening Assessments.

Cotswold District Council has measured concentrations of NO₂ above the annual mean objective at relevant locations outside of the existing AQMA, and **will need to proceed to a Detailed Assessment** for Thames Street, Lechlade.

3 Road Traffic Sources

Assessment of air quality is made at locations where experience from earlier rounds of reporting has shown that there is a risk of the national objective being exceeded. The Technical Guidance (LAQM.TG(09)) identifies the areas that should be considered.

3.1 Narrow Congested Streets with Residential Properties Close to the Kerb

A narrow congested street will be one with slow moving traffic that is frequently stopping and starting through much of the day, where the average speed is likely to be about 25 mph. A narrow street will be one with residential properties within 2m of the kerb with buildings on both sides of the road. The average daily traffic flow will be around 5,000 vehicles a day or more. (For more information see Box 5.3, LAQM.TG(09))

Thames Street, Lechlade meets these criteria. It is a narrow street with residential proprieties and slow moving traffic due to traffic control lights close together. Traffic flow is likely to be around 5,000 vehicles a day. Monitoring is already being undertaken and exceedance identified in 2008 for NO₂. Cotswold District Council is proceeding to a Detailed Assessment at this location.

Cotswold District Council has identified congested streets with a flow above 5,000 vehicles per day and residential properties close to the kerb, not adequately considered in previous rounds of Review and Assessment, and will need to proceed to a Detailed Assessment.

3.2 Busy Streets Where People May Spend 1-hour or More Close to Traffic

There will be some streets locations where individuals may regularly spend 1-hour or more, for example where there are many shops and outdoor cafes or bars. Assessment needs to consider only NO_{2.} Traffic flows would be in excess of 10,000 vehicles per day. (For more information see Box 5.3, LAQM.TG(09))

Within the AQMA declared for Birdlip at the Air Balloon roundabout there is a pubic house with a beer garden. Automatic monitoring is being undertaken at this site in 2009 as part of the Further Assessment and the 1-hour will be assessed. Diffusion tube monitoring is also being undertaken.

Cotswold District Council confirms that there are no new/newly identified busy streets where people may spend 1 hour or more close to traffic.

3.3 Roads with a High Flow of Buses and/or HGVs.

Cotswold District Council has declared an AQMA for NO₂ at the Air Balloon Roundabout a busy junction of the A417. This busy junction is the worst location in the district with a high number of HGV's at 11% of the total daily average traffic flow.

Cotswold District Council confirms that there are no new/newly identified roads with high flows of buses/HDVs.

3.4 Junctions

A "busy" junction is taken to be one with more than 10,000 vehicles per day. Cotswold District Council identified a busy junction on the Fosseway at Stow on the Wold and monitors for NO_2 by a cottage at this junction. AADT information identifies traffic flow at this location of 5,000 - 10,000. This is a diffusion tube at this location which reported a 2008 annual mean concentration of $36.2\mu g/m^3$. No further work is required at this site.

Cotswold District Council confirms that there are no new/newly identified busy junctions/busy roads.

3.5 New Roads Constructed or Proposed Since the Last Round of Review and Assessment

There have been no new roads and none planned that have not been considered.

Cotswold District Council confirms that there are no new/proposed roads.

3.6 Roads with Significantly Changed Traffic Flows

Roads that have significantly changed traffic flows that have not been considered in the previous sections are considered here.

Cotswold District Council confirms that there are no new/newly identified roads with significantly changed traffic flows.

3.7 Bus and Coach Stations

This sections applies to bus or coach stations that are not enclosed and where there is relevant exposure.

Cotswold District Council confirms that there are no relevant bus stations in the Local Authority area.

4 Other Transport Sources

A small number of local authorities had to consider other transport sources in previous rounds of reporting and any new work is required where there have been any significant changes.

4.1 Airport

Aircraft are considered to be potentially a significant source of NO₂. They have to be considered where there is relevant exposure and where there is high throughput of passengers in a year.

Cotswold District Council confirms that there are no airports in the Local Authority area.

4.2 Railways (Diesel and Steam Trains)

Railways with heavy traffic of diesel passenger trains have been identified in the Technical Guidance and supporting FAQ. Cotswold District does not have any of the busy railway lines within the district or any locations where there are stationary trains for any length of time.

4.2.1 Stationary Trains

Cotswold District Council confirms that there are no locations where diesel or steam trains are regularly stationary for periods of 15 minutes or more, with potential for relevant exposure within 15m.

4.2.2 Moving Trains

Cotswold District Council confirms that there are no locations with a large number of movements of diesel locomotives, and potential long-term relevant exposure within 30m.

4.3 Ports (Shipping)

Screening for shipping relates to large ships and busy ports. Cotswold District is land locked area.

Cotswold District Council confirms that there are no ports or shipping that meet the specified criteria within the administrative area.

5 Industrial Sources

5.1 Industrial Installations

Industrial sources are unlikely to make a significant local contribution to annual mean concentrations of pollutants; but may be significant in terms of the short term objectives district. There are no industrial areas within the district or close by that make a significant impact on the air quality. The industries within the district that emit any of the prescribed pollutants are not situated at locations of relevant public exposure.

5.1.1 New or Proposed Installations for which an Air Quality Assessment has been carried out

Cotswold District Council confirms that there are no new or proposed industrial installations for which planning approval has been granted within its area or nearby in a neighbouring authority.

5.1.2 Existing Installations where Emissions have Increased Substantially or New Relevant Exposure has been Introduced

Cotswold District Council confirms that there are no industrial installations with substantially increased emissions or new relevant exposure in their vicinity within its area or nearby in a neighbouring authority.

5.1.3 New or Significantly Changed Installations with No Previous Air Quality Assessment

Cotswold District Council confirms that there are no new or proposed industrial installations for which planning approval has been granted within its area or nearby in a neighbouring authority.

5.2 Major Fuel (Petrol) Storage Depots

There are no major fuel (petrol) storage depots within the Local Authority area.

5.3 Petrol Stations

This section assesses petrol stations that have an annual through put of more than 2000m ³ of petrol and also have a busy road nearby (more than 30,000 vehicles per day). There are no petrol stations with a throughput of petrol that exceeds the prescribed amount.

Cotswold District Council confirms that there are no petrol stations meeting the specified criteria.

5.4 Poultry Farms

This is a new area for consideration, PM $_{10}$ objectives have to be considered in the vicinity of poultry farms with a specified number of birds, a specific ventilation system and where relevant exposure exists.

Three poultry farms have been identified within the district; however they do not meet the criteria that would require further work. These are:

- A. Cedar Cable 100,000 places, two poultry houses cages for pullets;
- B. Clarke's Hill 90,000 poultry places-broiler chickens; and
- C. Leafield Farm Lechlade 200,000 places-broilers mechanically ventilated
 Unit A and Unit B the numbers of birds are below the threshold. Unit C The method of
 ventilation is mechanical

Cotswold District Council confirms that there are no poultry farms meeting the specified criteria.

6 Commercial and Domestic Sources

6.1 Biomass Combustion – Individual Installations

Biomass burning can lead to increased PM_{10} and NO_2 emissions. Cotswold District Council has identified one biomass boiler that has been installed. The unit is rated at 0.38MW. The unit is a BG100 type biomass generator using Talbott's C4 compression and is rated at 0.38MW. The stack height is 8.5m and the stack diameter is 0.4m. Particulate emissions have been provided as: 0.05g/s. Using the calculations from TG(09):

* Calculations

 PM_{10}

Chimney height -used actual 8.5m in accordance with Box 5.6

Background –adjusted emission rate ${}^*E_A = \underline{E}$ $E_A = \underline{0.05}$ = 0.00287g/s

(32-G) (32-14.58)

E is emission rate of plant = $50 \text{mg/m}^3 = 0.05 \text{g/s}$ G= annual average background $32 \mu \text{g/m}^3 = \text{annual average}$ concentration at which the 90^{th} percentile of 24hrs is likely to exceed the objective. background emission for location from AQ archive for $2009: 14.75 \mu \text{m}^3$

Using the nomogram (Fig. 5.19 TG (09)):

 *E_A – the "background–adjusted" emission rate is 0.00287g/s, which is less than the threshold emission rate for 8.5m chimney height = 0.0045 g/s. Therefore it will not be necessary to proceed to a detailed assessment.

Cotswold District Council has assessed the biomass combustion plant, and concluded that it will not be necessary to proceed to a Detailed Assessment for this boiler.

6.1.1 Biomass Combustion – Combined Impacts

Many small biomass combustion installations could in combination lead to unacceptably high PM₁₀ concentrations. Reviewing the criteria in the Technical Guidance and supporting FAQ there are no locations of concern within Cotswold District.

Cotswold District Council confirms that there are no biomass combustion plants in the Local Authority area.

6.2 Domestic Solid-Fuel Burning

No areas have been identified where domestic solid fuel gives rise to exceedences of the objective for SO₂ in previous Reviews and assessment. There are no areas of excessive domestic fuel use within the district that have been identified.

Cotswold District Council confirms that there are no areas of significant domestic fuel use in the Local Authority area.

7 Fugitive or Uncontrolled Sources

Fugitive emissions of dust where they would give rise to elevated concentrations of PM_{10} have not been found in the district. No new sites have received planning approvals that are potential source of fugitives or uncontrolled source since the last assessments. No complaints have been received regarding any dust sources.

Cotswold District Council confirms that there are no potential sources of fugitive particulate matter emissions in the Local Authority area.

8 Conclusions and Proposed Actions

8.1 Conclusions from New Monitoring Data

The conclusions from the monitoring data are that the Council will have to proceed to a Detailed Assessment for Thames Street, Lechlade as the annual mean concentration for 2008 is 43.4µg/m³. There is relevant exposure at this location as Thames Street is a narrow street with residential proprieties close to the kerb. Cotswold District Council will be submitting the results of the automatic and diffusion tube monitoring for 2009 currently being undertaken within the AQMA in the 2009 Further Assessment and 2010 Progress Report.

8.2 Conclusions from Assessment of Sources

There are no new local developments: road transport, other transport, industrial installations, commercial/domestic, fugitive emissions, residential and commercial that are likely to impact on the air quality in the district.

8.3 Proposed Actions

Cotswold District Council will be undertaking a Detailed Assessment for nitrogen dioxide in Thames Street Lechlade in 2010

Cotswold District Council will also undertake a Progress Report in 2010

Cotswold District Council will be submitting their Further Assessment towards the end of 2009.

Cotswold District Council is currently working on their AQAP aim to submit a draft at the end of 2009.

9 Appendix A: QA:QC Data

9.1 Diffusion Tube Bias Adjustment Factors

Diffusion tubes are supplied and analysed by Bristol Scientific Services. Tube preparation for nitrogen dioxide: are prepared using 50ul of 20% triethanolamine in water.

Benzene tubes are the Perkin Elmer type (length 89mm x 6.4mm o.d.) packed with Tenax TA. The uptake rate for benzene is taken to be 0.76 ng/ppm/min.

Cotswold District Council has not undertaken a co-location study, and used the national data base (Version 05/09). The bias adjustment factors utilised are:

- 2006 0.9 based on 5 studies,
- 2007 0.77 based on 5 studies,
- 2008 0.87 based on 4 studies.

9.2 QA/QC of automatic monitoring

Chemiluminesence analyser was supplied and maintained by AEA Energy and Environment. It was regularly calibrated by AEA staff using calibration gases certified to ISO17025. The data was collected and checked daily and was ratified at the end of the monitoring period by AEA. The type of analyser used has an expected accuracy of \pm 10% with precision of \pm 5 μ gm⁻³. There was some loss of data capture due to a failure and some intermittent with communication problems the data capture was 86%.

9.3 QA/QC of diffusion tube monitoring

Diffusion tubes are supplied and analysed by Bristol Scientific Services. Tube preparation for nitrogen dioxide: are prepared using 50ul of 20% triethanolamine in water. Benzene tubes are the Perkin Elmer type (length 89mm x 6.4mm o.d.) packed with Tenax TA. The uptake rate for benzene is taken to be 0.76 ng/ppm/minu

The laboratory participates in WASP scheme for nitrogen dioxide and benzene the result are given below (Table 7) and in field comparison studies with AEA Energy and Environment. The tube preparation and subsequent analysis follows the procedures in the harmonised "Practical Guidance" document.

Table 7: WASP results for Bristol Scientific Services

WASP Results Lab 152 Round 97 onwards:

Round	97	98	99	100	101	102	103	104
Tube 1 (μg NO ₂)	0.890	1.865	2.085	1.358	0.949	1.489	1.178	1.179
Tube 2 (μg NO ₂)	1.573	1.228	2.093	1.474	2.576	1.431	0.916	1.108
Tube 3 (μg NO ₂)	1.582	1.857	0.885	1.354	1.813	2.307	0.934	1.840
Tube 4 (μg NO ₂)	0.914	1.217	0.879	1.467	0.914	1.960	1.071	1.960
Spike tube 1 (μg NO2)	0.890	1.830	2.150	1.360	0.920	1.370	1.220	1.220
Spike tube 2 (µg NO2)	1.580	1.190	2.150	1.470	1.860	1.370	0.940	1.220
Spike tube 3 (µg NO2)	1.580	1.830	0.840	1.360	1.860	2.280	0.940	2.020
Spike tube 4 (µg NO2)	0.890	1.190	0.840	1.470	0.920	2.280	1.220	2.020
Standardised result tube 1	1.000	1.019	0.970	0.999	1.032	1.087	0.966	0.966
Standardised result tube 2	0.996	1.032	0.973	1.003	1.385	1.045	0.974	0.908
Standardised result tube 3	1.001	1.015	1.054	0.996	0.975	1.012	0.994	0.911
Standardised result tube 4	1.027	1.023	1.046	0.998	0.993	0.860	0.878	0.970
Performance index	1.87	5.29	16.61	0.08	374.65	73.42	41.98	45.95
Rolling performance index (NOT best of 4 out of 5)				5.96	99.16	116.19	122.53	134.00
Rolling performance index (best 4 out of 5)				5.96	5.96	23.85	33.02	40.36
Performance classification (criteria from April 2009)				Good	Good	Good	Good	Good
Good =<56.25								
Acceptable =<225								
Unacceptable >225								

10 Appendix B: List of Registered Processes

Table 8: List of LAPPC Permitted Installations on the Public Register

1 4510 01 210	The Larre remitted installations on the	T dbilo Tteglotei
A2/01	Northcot Brick Ltd Blockley	Brickworks
B1/04	Berite (Sawmills) Ltd Broadway Lane	Timber
B1/06	South Cernev Cotswold Garage Sheep Street	Waste Oil Burner
B1/07	Chipping Campden Peglars Garage London Road	Waste Oil Burner
B1/08	Tetburv Ivor Webb & Sons Cherry Tree Lane	Waste Oil Burner
B1/09	Cirencester N M Motors Bourton Industrial Estate	Waste Oil Burner
B1/11	Bourton on the Water RS Autos Querns Lane	Waste Oil Burner
B1/14	Cirencester Pulham & Son Coaches Ltd Station Road	Waste Oil Burner
B1/16	Bourton on the Water Chris Keen Old Staion Yard	Waste Oil Burner
B1/19	Ebrington Road Systematic Servicing Field House	Waste Oil Burner
B1/20	Willerslev N & N Autoworld Wilkinson Road	Waste Oil Burner
B1/22	Cirencester Transco Siddington	Natural Gas Odorisation
B1/23	Cirencester Bourton Vale Garage/Filling Station Station Road	Petrol Vapour Recovery
B1/24	Rourton on the Water Abbey Road Garage/Filling Station Gloucester Road	Petrol Vapour Recovery
B1/25	Cirencester Malthurst Filling Station Station Road	Petrol Vapour Recovery
B1/26	Stow-on-the-Wold Tesco Filling Station Kingsmeadow	Petrol Vapour Recovery
B1/28	Cirencester Barrington Filling Station A40	Petrol Vapour Recovery
B1/29	Barrington Malthurst Filling Station Burford Road	Petrol Vapour Recovery
B1/30	Cirencester Oldbury Hill Garage Didmarton	Petrol Vapour Recovery

Fairford Recovery	B1/32	Shell Filling Station	Petrol Vapour
B1/34 Marsh Service Station Stow Road (A429) Moreton in Marsh Recovery B1/36 New Quarry Motors Filling Station (Bridges Nissan) Recovery B1/38 Centurion Services Petrol Vapour Recovery B1/38 Centurion Services Petrol Vapour Recovery B1/39 Fosseway Service Station Petrol Vapour Recovery B1/40 Nower Staunhter Northfield Garage Petrol Vapour Recovery B1/41 Tethurv Recovery B1/41 Trooper's Lodge Filling Station Petrol Vapour Recovery B1/43 Somerfield / BP Service Station Petrol Vapour Recovery B1/44 Rourton on the Hill Somerfield / BP Service Station Petrol Vapour Recovery B1/45 Cotswold Garage Petrol Vapour Recovery B1/46 White Horse Filling Station Petrol Vapour Recovery B1/47 Cotswold Garage Petrol Vapour Recovery B1/48 Cotswold Garage Petrol Vapour Recovery B1/49 Cotswold Garage Petrol Vapour Recovery B1/40 Rourton Add Petrol Vapour Recovery B1/41 Cotswold Garage Petrol Vapour Recovery B1/42 Cotswold Garage Petrol Vapour Recovery B1/43 Cotswold Garage Petrol Vapour Recovery B1/44 Dapland Petrol Vapour Recovery B1/45 Cotswold Garage Petrol Vapour Recovery B1/46 White Horse Filling Station Petrol Vapour Recovery B1/47 Lating Add Petrol Vapour Recovery B1/48 Equipment Add Petrol Vapour Recovery B2/02 Hanson Premix Camental Add Animal Incinerator Posse Cross Industrial Estate North Cernev Hanson Premix Calgdon Pike Lephlarda Hanson Quarry Products Europe Ltd Quarrying Dadinworth Latarge Roofing Ltd Cement Broadway Lane South Cernev Longborough Concrete The Sitch Longborough Concrete The Sitch Longborough Concrete The Sitch Longborough Concrete The Sitch Animal Rourse Substrate SiRC Tetoury Steel Ltd London Road Tethury Aggregate Industries Building Products Di-isocyanate Broadway Lane Broadway Lane Broadway Lane Broadway Lane Substrate			
B1/34 Marsh Service Station Stow Road (A429) Moreton in Marsh Recovery B1/36 New Quarry Motors Filling Station (Bridges Nissan) B1/38 Centurion Services Centurion Services Gloucester Road (A417) Duntishourne Abhots Fosseway Service Station A429 B1/39 Fosseway Service Station A429 B1/40 Northfield Garage London Road Tethurv B1/41 Trooper's Lodge Filling Station A444 Recovery B1/43 Somerifield / BP Service Station B1/44 Somerifield / BP Service Station B1/45 Cotswold Garage B1/46 White Horse Filling Station B1/46 Perrol Vapour Recovery B1/48 Ferminan Amsell Equine and Pet Services Ltd Fosse Cross Industrial Estate North Cennev Hanson Premix Claydon Pike I achiaria B2/05 Hanson Quarry Products Europe Ltd Daglingworth Ouarry Danlisworth Lafarge Roofing Ltd Broadway Lane South Cernev Longborough Concrete The Sitch Londborouch B2/17 Shorncote Quarry Someriord Keynes B3/02 Agricultural Supply Company Ltd Welsh Way Substrate B3/03 Site During Station Products B1/05 Februry Steel Ltd London Road Tethury B3/05 Agricultural Supply Company Ltd Welsh Way Substrate B3/03 Site During Steel Ltd London Road Tethury Aggregate Industries Building Products Broadway Lane B3/05 Broadway Lane B3/06 Di-isocyanate B3/07 Di-isocyanate	B1/33	A40	•
B1/38 Chesterton I ane Centurion Services Gloucester Road (A417) Recovery Chesterton I ane Centurion Services Gloucester Road (A417) Recovery Duntishourne Abhots Fosseway Service Station A229 Recovery I lower Slaunhter Northfield Garage London Road Recovery Tethury Trooper's Lodge Filling Station Petrol Vapour Recovery Tethury Trooper's Lodge Filling Station Petrol Vapour A444 Recovery Recovery B1/41 Somerfield / BP Service Station Petrol Vapour A444 Recovery Recovery Runfon on the Hill Somerfield / BP Service Station Petrol Vapour Harebushes Recovery Runfon Road Quarry Hill Service Station Petrol Vapour Recovery Runfon Road Quarry Hill Service Station Petrol Vapour Recovery Sheep Street Recovery	B1/34	Marsh Service Station	•
B1/38 Centurion Services Gloucester Road (A417) Recovery B1/39 Fosseway Service Station A429 Petrol Vapour A229 B1/40 Northfield Garage London Road Recovery B1/41 Terbirry Trooper's Lodge Filling Station Petrol Vapour Recovery B1/43 Somerfield / BP Service Station Petrol Vapour Recovery B1/44 Somerfield / BP Service Station Petrol Vapour Recovery B1/45 Somerfield / BP Service Station Petrol Vapour Recovery B1/46 Quarry Hill Service Station Petrol Vapour Recovery B1/45 Cotswold Garage Recovery B1/46 Cotswold Garage Petrol Vapour Recovery B1/46 Cotswold Garage Petrol Vapour Recovery B1/48 Equine and Pet Services Ltd Petrol Vapour Recovery B1/48 Equine and Pet Services Ltd Posse Cross Industrial Estate North Cernev Hanson Premix Claydon Pike Lachlade Hanson Quarry Products Europe Ltd Quarrying Daglingworth Quarry B2/05 Hanson Quarry Products Europe Ltd Quarrying Daglingworth Quarry B2/06 Lachlade Hanson Quarry Products Europe Ltd Cement Proadway Lane South Cernev Ladarge Roofing Ltd Cement Products Cement The Sitch Lanchorauch Huntsmans Quarries Ltd Broadway Lane South Cement Shorncote Quarry Somerford Keynes B3/02 Agricultural Supply Company Ltd Mushroom Substrate SulAC Tetbury Steel Ltd London Road Tethury Aggregate Industries Building Products Broadway Lane B3/05 Signatural Supply Company Ltd Metal Coating London Road Tethury Aggregate Industries Building Products Di-isocyanate Broadway Lane B3/05 Broadway Lane Barden Barden Building Products Di-isocyanate Broadway Lane Broadway Lane Broadway Lane Broadway Lane Broadway Lane Barden Bar	B1/36	(Bridges Nissan)	•
B1/39 Fosseway Service Station A429 Recovery B1/40 Northfield Garage Petrol Vapour A29 Recovery B1/41 Northfield Garage Petrol Vapour A29 Recovery B1/41 Troper's Lodge Filling Station A44 Recovery B1/43 Rourton on the Hill Somerfield / BP Service Station Harebushes Rurford Road B1/44 Quarry Hill Service Station B1/45 Cotswold Garage B1/46 Cotswold Garage B1/46 White Horse Filling Station A419 Recovery B1/48 Equinon Campden White Horse Filling Station A419 Framnton Mansell Equine and Pet Services Ltd Fosse Cross Industrial Estate North Cernev Hanson Premix Cement Claydon Pike Lechlarde B2/05 Hanson Quarry Products Europe Ltd Daglingworth Quarry Daglingworth Quarry Daglingworth Cement B2/08 Longborough Concrete The Sitch Longborough Concrete The Sitch Longborough Concrete The Sitch Longborough Concrete The Sitch B2/09 Agricultural Supply Company Ltd Welsh Way Surbhill Cirencester B3/02 Agricultural Supply Company Ltd Welsh Way Surbhill Cirencester B3/03 SiAC Tetbury Steel Ltd London Road Tethurv Aggregate Industries Building Products Broadway Lane B3/05 Agricultural Supply Company Ltd Welsh Way Surbhill Cirencester B3/03 SiAC Tetbury Steel Ltd London Road Tethurv Aggregate Industries Building Products Broadway Lane B3/05 Agricultural Supply Company Ltd Recovery Bayon Bayon Bayon Bayon Bayon Bayon Bayon Betrol Vapour Recovery Petrol Vapour Recovery Rec	B1/38	Centurion Services Gloucester Road (A417)	•
B1/40 Northfield Garage London Road Recovery B1/41 Trooper's Lodge Filling Station A44 Recovery B1/43 Somerfield / BP Service Station Petrol Vapour Recovery B1/44 Rourton on the Hill Somerfield / BP Service Station Petrol Vapour Recovery B1/45 Rurford Road Quarry Hill Service Station Petrol Vapour Recovery B1/46 Cotswold Garage Petrol Vapour Recovery B1/46 Petrol Vapour Recovery B1/46 Petrol Vapour Recovery B1/48 Equine and Pet Services Ltd Animal Incinerator Fosse Cross Industrial Estate North Cernev Lanson Premix Cement Claydon Pike B2/02 Hanson Premix Cement Quarrying Dadiloworth Lafarge Roofing Ltd Quarrying Dadiloworth Quarry Dadiloworth Quarry Dadiloworth Currev South Cernev Longborough Concrete Cement The Sitch Inondhorough Huntsmans Quarries Ltd Quarrying B2/08 Longborough Concrete Cement Naunton Shorncote Quarry Somerford Keynes B2/07 Agricultural Supply Company Ltd Mushroom Substrate SulAC Tetbury Steel Ltd London Road Tethurv Aggregate Industries Building Products Di-isocyanate Broadway Lane	B1/39	Fosseway Service Station A429	•
B1/41 Trooper's Lodge Filling Station A44 Recovery B1/43 Bourton on the Hill Somerfield / BP Service Station Petrol Vapour Recovery B1/44 Repushes Recovery B1/44 Quarry Hill Service Station Petrol Vapour Recovery B1/45 Cotswold Garage Petrol Vapour Recovery B1/46 Cotswold Garage Petrol Vapour Recovery Chipping Campden Recovery B1/46 White Horse Filling Station Petrol Vapour Recovery Framotron Mansell Require and Pet Services Ltd Animal Incinerator Fosse Cross Industrial Estate North Cernev Hanson Premix Cement Claydon Pike I achitarle Hanson Quarry Products Europe Ltd Quarrying Daglingworth Quarry Dardinworth Lafarge Roofing Ltd Recovery Longborough Concrete The Sitch Longborough Concrete The Sitch Sounds Quarries Ltd Quarrying B2/09 Huntsmans Quarries Ltd Quarrying B2/07 Agricultural Supply Company Ltd Mushroom Shorncote Quarry Somerford Keynes B3/02 Agricultural Supply Company Ltd Mushroom Substrate Sinch I Cirencester SIAC Tetbury Steel Ltd London Road Tethury Aggregate Industries Building Products Di-isocyanate Broadway Lane	B1/40	Northfield Garage London Road	•
B1/43 Somerfield / BP Service Station Recovery Harebushes Runford Road Quarry Hill Service Station Petrol Vapour Recovery B1/44 Quarry Hill Service Station Petrol Vapour Recovery B1/45 Cotswold Garage Petrol Vapour Sheep Street Recovery Entrol Vapour Recovery B1/46 White Horse Filling Station Petrol Vapour Recovery B1/48 Framoton Mansell Equine and Pet Services Ltd Animal Incinerator Fosse Cross Industrial Estate North Cernev Hanson Premix Cement Claydon Pike Perchlarle Hanson Quarry Products Europe Ltd Quarrying Daglingworth Quarry Daglingworth Lafarge Roofing Ltd Cement B2/05 Baroadway Lane South Cernev Longborough Concrete Cement The Sitch Londborough B2/09 Huntsmans Quarries Ltd Quarrying B2/17 Somerford Keynes B3/02 Agricultural Supply Company Ltd Mushroom Substrate B3/03 Agricultural Supply Company Ltd Mushroom Welsh Way Substrate B3/05 Aggregate Industries Building Products Di-isocyanate Broadway Lane Di-isocyanate Broadway Lane Di-isocyanate Baroadway Lane Da-isoc	B1/41	Trooper's Lodge Filling Station A44	•
B1/44 Quarry Hill Service Station Bourton-on-the-Hill B1/45 Cotswold Garage Sheep Street Chinoina Camnden White Horse Filling Station A419 Framotion Mansell Equine and Pet Services Ltd Fosse Cross Industrial Estate North Cernev Hanson Premix Claydon Pike Lechlarle Hanson Quarry Products Europe Ltd Daglingworth Quarry Dardinworth Lafarge Roofing Ltd Broadway Lane South Cernev Longborough Concrete The Sitch Londonoruah Huntsmans Quarries Ltd B2/09 B2/07 B2/08 B2/08 B2/09 B2/08 B2/09 B2/08 B2/09 B2/09 B2/07 B2/07 B2/07 B2/07 B2/08 B2/08 B2/09 B2/08 B2/09 B2/08 B2/09 B2/07	B1/43	Somerfield / BP Service Station Harebushes	•
Sheep Street Chinoino Camorden White Horse Filling Station A419 B1/48 B1/48 B1/48 B1/48 B2/02 B2/02 B2/02 B2/05 B2/05 B2/06 B2/06 B2/06 B2/06 B2/08 B2/08 B2/08 B2/08 B2/08 B2/08 B2/08 B2/08 B2/09 B2/08 B2/09 B2/08 B2/09 B2/08 B2/09 B2/08 B2/09 B2/08 B2/09 B3/00 B2/09 B3/02 Agricultural Supply Company Ltd Welsh Way Substrate B3/02 B3/03 B3/03 B3/03 B3/03 B3/03 B3/03 B3/05 B3/06 B3/07 B3/08 B3/	B1/44	Quarry Hill Service Station	•
B1/46 White Horse Filling Station A419 Recovery Framnton Mansell Equine and Pet Services Ltd Fosse Cross Industrial Estate North Cernev Hanson Premix Claydon Pike Lechlade Hanson Quarry Products Europe Ltd Daglingworth Quarry Dardinworth Lafarge Roofing Ltd Broadway Lane South Cernev Longborough Concrete The Sitch Lonchorounh Huntsmans Quarries Ltd Buckle Street Naunton Shorncote Quarry Somerford Keynes B3/02 Agricultural Supply Company Ltd Welsh Way Substrate Sinhill. Cirencester SIAC Tetbury Steel Ltd London Road Tethurv Aggregate Industries Building Products Di-isocyanate Broadway Lane Di-isocyanate	B1/45	Sheep Street	•
B1/48 Equine and Pet Services Ltd Animal Incinerator Fosse Cross Industrial Estate North Cernev Hanson Premix Cement Claydon Pike Lechlade Hanson Quarry Products Europe Ltd Quarrying Daglingworth Quarry Daglingworth Lafarge Roofing Ltd Cement Broadway Lane South Cernev Longborough Concrete The Sitch Londborough Huntsmans Quarries Ltd Quarrying Buckle Street Naunton Shorncote Quarry Somerford Keynes B3/02 Agricultural Supply Company Ltd Mushroom Welsh Way Substrate Sinhill. Cirencester SIAC Tetbury Steel Ltd London Road Tethurv Aggregate Industries Building Products Di-isocyanate Broadway Lane	B1/46	White Horse Filling Station A419	•
B2/02 Hanson Premix Claydon Pike I erchlarde Hanson Quarry Products Europe Ltd Quarrying Daglingworth Quarry Danlinworth Lafarge Roofing Ltd Cement Broadway Lane South Cernev Longborough Concrete The Sitch I onnborough Huntsmans Quarries Ltd Quarrying Buckle Street Naunton B2/17 Shorncote Quarry Somerford Keynes B3/02 Agricultural Supply Company Ltd Mushroom Welsh Way Substrate Sinhill. Cirencester SIAC Tetbury Steel Ltd London Road Tethurv Aggregate Industries Building Products Broadway Lane	B1/48	Equine and Pet Services Ltd Fosse Cross Industrial Estate	Animal Incinerator
B2/05 Hanson Quarry Products Europe Ltd Quarrying Daglingworth Quarry B2/06 Lafarge Roofing Ltd Cement Broadway Lane B2/08 South Cernev Longborough Concrete The Sitch Londborough Huntsmans Quarries Ltd Quarrying Buckle Street Naunton Shorncote Quarry Somerford Keynes B3/02 Agricultural Supply Company Ltd Mushroom Welsh Way Substrate Suphill Cirencester SIAC Tetbury Steel Ltd London Road Tethurv Aggregate Industries Building Products Broadway Lane Di-isocyanate	B2/02	Hanson Premix Claydon Pike	Cement
B2/06 Lafarge Roofing Ltd Broadway Lane South Cernev Longborough Concrete The Sitch Longborough Huntsmans Quarries Ltd B2/09 Huntsmans Quarries Ltd B2/17 Shorncote Quarry Somerford Keynes B3/02 Agricultural Supply Company Ltd Welsh Way Substrate Sinhill. Cirencester SIAC Tetbury Steel Ltd London Road Tethurv Aggregate Industries Building Products Broadway Lane Cement Cement Cement Mobile Crusher Auarrying Mobile Crusher Mobile Crusher Substrate Substrate Substrate Substrate Di-isocyanate	B2/05	Hanson Quarry Products Europe Ltd Daglingworth Quarry	Quarrying
B2/08 Longborough Concrete The Sitch Longborough Huntsmans Quarries Ltd B2/09 Huntsmans Quarries Ltd Guarrying Buckle Street Naunton Shorncote Quarry Somerford Keynes B3/02 Agricultural Supply Company Ltd Welsh Way Substrate Sunhill. Cirencester SIAC Tetbury Steel Ltd London Road Tethurv Aggregate Industries Building Products Broadway Lane Cement Cement Cement Cement Cement Auarrying Mobile Crusher Mobile Crusher Mushroom Substrate Mushroom Substrate Sunhill Coating Di-isocyanate	B2/06	Lafarge Roofing Ltd Broadway Lane	Cement
B2/09 Huntsmans Quarries Ltd Quarrying Buckle Street Naunton Shorncote Quarry Somerford Keynes B3/02 Agricultural Supply Company Ltd Mushroom Welsh Way Substrate Sunhill. Cirencester SIAC Tetbury Steel Ltd Metal Coating London Road Tethurv Aggregate Industries Building Products Broadway Lane Quarrying Quarrying Mobile Crusher Mushroom Substrate Mushroom Di-isocyanate	B2/08	Longborough Concrete The Sitch	Cement
B2/17 Shorncote Quarry Somerford Keynes B3/02 Agricultural Supply Company Ltd Welsh Way Substrate Sunhill. Cirencester SIAC Tetbury Steel Ltd London Road Tetburv Aggregate Industries Building Products Broadway Lane Mobile Crusher Mushroom Substrate Metal Coating Metal Coating Di-isocyanate	B2/09	Huntsmans Quarries Ltd Buckle Street	Quarrying
Welsh Way Substrate Sunhill_Cirencester SIAC Tetbury Steel Ltd London Road Tetbury Aggregate Industries Building Products Broadway Lane Substrate Metal Coating Di-isocyanate	B2/17	Shorncote Quarry	Mobile Crusher
B3/03 SIAC Tetbury Steel Ltd Metal Coating London Road Tetburv Aggregate Industries Building Products Broadway Lane Metal Coating Di-isocyanate	B3/02	Welsh Way	
B3/05 Aggregate Industries Building Products Di-isocyanate Broadway Lane	B3/03	SIAC Tetbury Steel Ltd London Road	Metal Coating
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	B3/05	Aggregate Industries Building Products	Di-isocyanate

B3/06	K L Evesham Ltd	Wood Coating
	Weston Trading Estate	
B3/09	Waston-sub-Edga Mitsubishi Motors Ltd	Vehicle Coating
D3/09	Elliot Road	verlicie Coating
	Cirencester	
B3/13	Haines & Strange (Cirencester) Ltd	Vehicle Coating
	Midland Road	
B3/17	Cirencester	Coating of Motal
D3/1/	Industrial Shotblast & Spraying Ltd, Tetbury	Coating of Metal
B3/18	Mary's Laundry, High Street, Bourton on the Water	Dry Cleaning
B3/19	Cotswold Concrete Ltd, Shornecote, Somerford	Cement
D3/19	Keynes	Cement
	Neyries	
B3/20	Johnson Cleaners, 14 Market Place,	Dry Cleaning
	Cirencester	
B3/21	Waterloo Dry Cleaners Ltd.	Dry Cleaning
D3/21	6 The Waterloo Cirencester	Dry Oleaning
B3/22	Martins Dry Cleaners	Dry Cleaning
l	Cricklade Street	
B3/23	Russells Dry Cleaner	Dry Cleaning
DO, EC	THEREALT ENG CHANKS	Ви сжинии
B3/24	Hanson Premix, Coln Gravel	Bulk Cement
	Clavdon Pike. Lechlade	
B3/25	The Dry Cleaning Co, Unit 1	
D0/20	Hospital Boad Moreton-in- Marsh	Dry Cleaning
		·

11 Appendix C - Maps of monitoring locations




Figure 3: Cotswold monitoring sites



Figure 4: Todenham Road monitoring site




Figure 5: Birdlip monitoring sites




Figure 6: Bourton-on-the-Water monitoring site




Figure 7: Cirencester monitoring sites



Figure 8: Fairford monitoring sites




Figure 9: Lechlade monitoring site




Figure 10: Moreton-in-Marsh monitoring site




Figure 11: Stow Lodge monitoring site




Figure 12: Stow-in-the-Wold monitoring site




Figure 13: Tetbury monitoring site